# *SW-II & PR-II*
USB DRIVER INSTALL

Manual

Date : 2017. 06. 19

# SW-II & PR-II USB Driver Manual

<O/S : Windows 7>

1. Check if HOLTEK USB PORT is shown in Control Panel-Device Manager as below when connecting PC or POS via USB.

2. Install "USBBridgeSetup.exe" driver installation file as below if Holtek USB COM Port is not shown.

SW-II & PR-II USB Driver Manual

3. Check if HOLTEK USB COM PORT is shown in Device Manageer after installing Driver and then rebooting PC.

SW-II & PR-II USB Driver Manual

## <O/S : Over Windows 8 version>

1. Shift + Restart


2. Choose an option – Troubleshoot

3. Troubleshoot – Advanced options

4. Advanced options – Startup Settings

5. Restart

6. Choose Disable Driver signature Enforcement

7. Install "USBBridgeSetup.exe" driver installation file.